# HOW TO COMPLETE THE CAIP INSPECTED UNITS FORM

## The FMCSA provides data via its Safety Measurement System (SMS)

#### 1. Go to safer.fmcsa.dot.gov

2. Scroll down and click the Company Snapshot link under the center column, titled FMCSA Searches

FMCSA Services	FMCSA Searches	Other FMCSA Web Sites
EMCSA Registration & Updates	<u>Company Snapshot</u>	FMCSA Home Page
Online Fine Payment	Analysis & Information (A&I) Online	DataQs
MCMIS Data Dissemination Catalog/Company Safety Profiles	Licensing & Insurance	<u>FMCSA Information Systems</u>

### 3. Enter the applicant's USDOT, MC/MX Number or Name then select Search

Company Snapshot						
The Company Snapshot is a concise electronic record of a company's identification, size, commodity information, and safety record, including the safety rating (if any), a roadside out-of-service inspection summary information. The Company Snapshot is available via an ad-hoc query (one carrier at a time) free of charge.	, and crash					
Search Criteria						
Users can search by DOT Number, MC/MX Number or Company Name.						
USDOT Number O MC/MX Number Name Enter Value:  Search						

#### 4. Once the Company Snapshot comes up, select SMS Results

USDOT Numb	er OMC/MX Number OName		C	ompany Snapshot				
Enter Val	ue:		84 TO	MANN CN TERMINES LLC				
	Search			USDOT Number:				
ID/Operations   Inspections/Crashes In US   Inspections/Crashes In Canada   Safety Rating								
Carriers: If you would like to update the following ID/Operations information, please complete and submit form <u>MCS-150</u> which can be obtained <u>online</u> or from your State SMS Results FMCSA office. If you would like to challenge the accuracy of your company's safety data, you can do so using FMCSA's <u>DataQs</u> system.								
Carrier and other users: FMCSA provides the Company Safety Profile (CSP) to motor carriers and the general public interested in obtaining greater detail on a particular motor carrier's safety performance then what is captured in the Company Snapshot. To obtain a CSP please visit the CSP order page or call (800)832-5660 or (703)280-4001 (1) (Fee Required).								
For help on the explanation of individual data fields, click on any field name or for help of a general nature go to SAFER General Help.								
The information below reflects the content of the FMCSA management information systems as of 07/30/2019. Carrier VMT Outdated.								
	]							
Entity Type:	CARRIER			4				
Operating Status:	ACTIVE	Out of Service Date: N	lone					
Legal Name:								
DRA Name:								

5. On the SMS Results page, scroll down and select <u>Downloads</u> to bring up download options. Leave the default set to <u>Focus: All</u> and select your preferred File Type. Select <u>Download</u>.

	For U.S. DOT#		Downloads .
	Complete SMS Profile	$\ominus$	Select a focus and file type to download SMS data.
	Carrier History	$\ominus$	Focus: All V File Type:
*	Downloads	⊝	Excel V DOWNLOAD

6. After opening the downloaded file, select the <u>Inspections</u> tab. The Inspections tab will display the vehicle identification number (VIN) inspected by the FMCSA and operated by the carrier.

A	lutoSave 💽	off (	5-6-6	) =		USDO	_All_BASICs_Public_0	6-28-2019 - Read-Only - Excel		
File Home Insert Page Layout Formulas Data Review View Help 🔎 Tell me what you want to do										
Pa	>n ∦ .□ [≞ - ste ダ	Arial B I	+ 10 □ +   ⊞ +   <u>&lt;</u>	• A^ A*	= = <b>=</b> ≫. = = = = = =	않 Wrap Text	General Freeze Panes * \$ * %		t as Cell	Insert
Clip	board 🗔		Font	G.	Align	ment	Freeze Nu	mber 🖫 Styles		
A1 $\checkmark$ : X $\checkmark$ $f_x$ Report										
	А	в	с	D	E	F	G	н	1	
1				Repo	ort					
2	Date	State	Number	ا مرما	Placardable HM	HM Inspection	BASIC	Violation Group Description	Code	Desc
3	5/16/2019	PA	Number	2	No	No	Vehicle Maint	Brakes All Others	393 45(b)(2)	Brak
4	5/16/2019	PA		2	No	No	Vehicle Maint.	Clearance Identification Lamps/Other	393.9	Inope
5	5/2/2010	ст		2	No	No	Vehicle Maint	Clearance Identification	202.0	Inone
5	5/2/2019	CT		2	No	No	HOS Compliance	Incomplete/Wrong Log	395 8E01	Drive
7	5/2/2019	CT		2	No	No	HOS Compliance	FOBR Related	395 22H1	Drive
8	5/2/2019	СТ		2	No	No	HOS Compliance	EOBR Related	395.22H3	Drive malfu
9	5/2/2019	СТ		2	No	No	Vehicle Maint.	Wheels, Studs, Clamps, Etc.	396.3(a)(1)	Inspe acce
10	4/15/2019	DE	Statement Street	2	No	No	Vehicle Maint.	Tires	396.3A1T	Tires
11	4/15/2019	DE	-	2	No	No	HOS Compliance	Other Log/Form & Manner	395.15(i)(5)	Onbc inforr
12	4/3/2019	RI	Received and the	1	No	No				
13	3/18/2019	NY		2	No	No	Vehicle Maint.	Emergency Equipment	393.95(f)	No /
14	3/18/2019	NY		2	No	No	Vehicle Maint.	Lighting	393.9(a)	Inope
15	3/18/2019	NY		2	No	No	Vehicle Maint.	Tires	393.75(a)(3)	Tire-f
16	3/18/2019	NY		2	No	No	Vehicle Maint	Reflective Sheeting	393 11TI	Truck sheet
10	0/10/2013			~		110	veniere mant.	Clearance Identification	<b>V</b>	Venile
	•	Ove	rview Violation	n Summary	Inspections	Crashes Acute-Cri	tical Violations	÷ : •	1	

7. Each unit inspected in the preceding 12-months must be listed on the CAIP Inspected Units Form. The VIN number should be listed only once and can be copied from the downloaded file to the CAIP Inspected Units Form.

For units owned and sold prior to the policy inception, a bill of sale should accompany the application. The Estimated Cost of Hire provided on the application should include an estimate of the annualized Cost of Hire for each vehicle the applicant will operate during the policy term.